Sanitized Copy Approved for Release 2011/08/31 : CIA-RDP80-00809A000600330517-1

DEC. 1948

CLASSIFICATION

CONFIDENTIALCONFIDENTIAL

REPORT

50X1-HUM

CENTRAL INTELLIGENCE AGENCY

INFORMATION FROM FOREIGN DOCUMENTS OR RADIO BROADCASTS

COUNTRY

USSR

DATE OF

CD NO.

INFORMATION 1950

DATE DIST. 7 Aug. 1950

**SUBJECT** 

Scientific - Vacuum tubes; radio, television

HOW

PUBLISHED Monthly periodical

WHERE

PUBLISHED Moscow

\_\_\_\_

DATE

PUBLISHED Mar 1950

LANGUAGE Russian

NO. OF PAGES 2

SUPPLEMENT TO

REPORT NO.

THIS DOCUMENT CORTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES WITHIN THE MEANING OF ESPIONASE ACT SO U. S. C., 31 AND 32, A5 AMENDED. ITS TRANSMISSION OF THE REVIELLATION OF ITS CONTRETS IN ANY BANNER TO AN UNAUTHORIZED PERSON IS PRO-MISITED BY LAW. REFROUCTION OF THIS FORM IS PROHIBITED.

THIS IS UNEVALUATED INFORMATION

SOURCE

Radio, No 3, 1950.

## NEED OF QUALITY TUBES FOR TELEVISION SETS

In recent years our radio industry has put out several television models. In Moscow and Leningrad, where television centers operate regularly, there are a large number of commercial and amateur television sets. Each owner has a right to expect long uninterrupted service from his set.

As we all know, the reliability of radio apparatus depends first of all on the quality of its parts and tubes. However, in this respect, matters are far from satisfactory. For example, the G-411 tube is most often used in line scanning. Frequently, this tube is not available in the shops. However, the main trouble is not scarcity but the fact that a large percentage of these tubes are of very poor quality. The Central DOSARM Club obtained 20 G-411 tubes. When tested in the "Leningrad T-1" television set and the "Moskvich T-1," 25 percent were found to be unsuitable.

The main defects of the G-411 tube are: poor quality of the glue in the base, insufficient exhaustion, and considerable variation of parameters. In spite of very careful handling, the base soon comes off; in operation, the tube often becomes gassy; and the considerable variation of its parameters makes it unsatisfactory for use as a sweep generator due to the appreciable fluctuations in the line frequency and high voltage on the picture tube. As a result, the line frequency often gets beyond control limits and it becomes necessary to select different circuit elements for each individual tube. Moreover, the G-411 does not have a standard base and the tube panels for such bases are not on sale.

Through the pages of the <u>Radio</u>, we appeal to the <u>Ministry</u> of the Communications Equipment Industry and to the collective of radio tube plants to take up the question of improving the quality of tubes for television sets, particularly, sweep generators and output tubes for systems with separate generators. It is essential that all these tubes have standard bases.

## CONFIDENTIAL

- 1 -

CLASSIFICATION		CONFIDENTIAL		 <del></del>
STATE NAVY NSRB	1	DISTRIBUTION	0	

Sanitized Copy Approved for Release 2011/08/31 : CIA-RDP80-00809A000600330517-1

## CONFIDENTIAL

CONFIDENTIAL

50X1-HUM

Considering the rate at which television is developing, it is not possible to defer solution of problems connected with the production of quality tubes for television sets. Solution of these problems will relieve the radio amateur of hunting for tubes for his television set and will free the television repair shops from having to send out their expert personnel to change radio tubes which have become defective before the expiration of the factory guaranteed period. Letter to the editor, signed by A. Korniyenko, B. Levandovskiy, and N. Kuznetsov, Moscow.

- E N D -

- 2 - CONFIDENTIAL